

Survey of Edinburgh and Glasgow properties following death.

IBIS assisted STATS with the completion of the survey and reporting of 18 properties that incorporated stone masonry facades, mostly traditionally built around or before the turn of the 20th Century. Following assessment by the stone masonry expert using roped access, short and long term repair and maintenance advice has been provided and dangerous stone identified and, in some cases, immediately removed. The enquiry into the death at Ryan's Bar on Hope Street, Edinburgh, has just been completed with 'shoddy' stone fixing blamed for the death.

